

Darrington Church of England Primary School Denby Crest, Darrington, Pontefract, West Yorkshire, WF8 3SB Telephone: (01977) 232320 Fax: (01977) 722637 Email: admin@darringtonschool.org.uk Headteacher: Mrs L Ranby, BA (Hons) PGCE NPQH



LOCAL OFFER FOR SEND – ACCESSIBILITY CHECKLIST

| | YES | NO | PART |
|---|--------------|----|------|
| Signage | | | |
| External signage from road to entrance is clear and well placed. | \checkmark | | |
| Internal signage is clear and well placed. | ✓ | | |
| Accessible Parking | | | |
| Accessible parking signed and available for people with disabilities (from April 2015) | \checkmark | | |
| Number of spaces | 1 | | |
| Main Entrance | | I | |
| Well signed from edge of school grounds and easily recognised. | \checkmark | | |
| Entry systems at correct height/position with sufficient space for a wheelchair. | ✓ | | |
| Floor coverings do not impede access through the door. | \checkmark | | |
| Reception counter accessible (height, position of writing surface). | \checkmark | | |
| Circulation: Horizontal | | | |
| Flat access around school, along corridors and through doors (internal and external), ie, raised thresholds/door sills no more than 15mm total height, any vertical surface 5mm maximum. | ✓ | | |
| Ramps meet guidelines (gradient, kerbs, handrails, width). | N/A | | |
| Adequate corridor width for volume of people. | \checkmark | | |
| All doors wide enough for wheelchair users (single, clear opening width). | \checkmark | | |
| All doors open without excessive pressure, or magnetically operated | \checkmark | | |
| Circulation: Vertical | | | |
| Handrails on both sides of stairs, continuous around | N/A | | |
| landings (except at the lift). | | | |
| Lift convenient to use (size, controls). | N/A | | |
| Emergency evacuation procedures for disabled in place for upper floors. | N/A | | |

| | YES | NO | PART |
|---|--------------|-----|------|
| Accessible toilet/hygiene room | | | |
| Number available | 2 | | |
| Signage in place. | \checkmark | | |
| Adequate dimensions (minimum 2200mm x 1500mm), | \checkmark | | |
| adequate turning space | | | |
| WC and fittings correctly placed (grab rails, wash basin, | \checkmark | | |
| mirror, light switch, hook). | | | |
| Alarm system functions correctly and ready for use. | | Х | |
| Colour contrasted fittings, etc. | | Х | |
| Toilet ready for use at all times (not used for temporary | \checkmark | | |
| storage, etc). | | | |
| Hoist facilities available | | Х | |
| Changing bench (height adjustable). | \checkmark | | |
| Shower facilities | \checkmark | | |
| Measures for hearing impairment | | | |
| Classrooms are carpeted or have appropriate surface | \checkmark | | |
| Emergency systems have visual alarms | | Х | |
| Technical aids (eg, hearing loop at entrance desk, | | Х | |
| soundfield system in place if appropriate | | | |
| Measures for visual impairment | | | |
| Good levels of natural/artificial lighting. | \checkmark | | |
| Blinds/anti-glare glazing where needed. | \checkmark | | |
| Surfaces are non-reflective | \checkmark | | |
| Colour contrasting décor. | \checkmark | | |
| Stairs, steps, kerbs, level changes colour contrasted | | Х | |
| (internal and external). | | | |
| Braille is used where appropriate, eg, for lift controls | | N/A | |
| (inside and outside). | | | |
| Additional resource room | | | |
| Quiet distraction-free withdrawal/work areas). | \checkmark | | |
| Room available for visiting therapists/health care. | \checkmark | | |
| Medical room | | Х | |